

Get into Fastboot or Recovery

Using ADB commands

Recovery Mode

```
adb reboot recovery
```

Fastboot/Bootloader Mode

```
adb reboot bootloader
```

Using device buttons

This applies to all OnePlus devices including OnePlus 6T:

Fastboot mode

- Power off the device.
- Press and hold **Volume Up + Power button**.
- Release the **Power button** when you see the OnePlus logo and keep holding the **Volume Up button** until you see the fastboot mode splash screen.

Recovery mode

- Reboot to fastboot mode as shown above.
- In the fastboot mode, use the **Volume keys** to navigate to Recovery Mode and use the **Power button** to select it.
- Alternatively, with the device powered off, press and hold **Volume Down + Power button** until you see the OnePlus logo.

From:
<https://wiki.oscardegroot.nl/> - HomeWiki

Permanent link:
<https://wiki.oscardegroot.nl/doku.php?id=android:oneplus:enter-fastboot-recovery&rev=1600275408>

Last update: **2022/01/15 11:38**

